

Staging

Upper			Session 1	Session 2	Session 3	Session 4
			13:30-16:00	13:30-16:00	13:30-16:00	13:30-16:00
Pass	SUNS	Start	101	-	108	101
		End	-	158>108	152>101	152>101
Exp Gds	SHAS	Start	200	293	-	200
		End	285>293	-	264>200	200
	ONVP	Start	-	263>264	237	-
		End	-	264	-	->236>237>-
Ore	IRHL	Start	205	205	205	205
		End	260>842>205	205	205	260>842>205

Lower						
Pass	HORP	Start	-	104	-	-
		End	101>104	-	-	->101>104>-
Exp Gds	FLPA	Start	285	263	285	285
		End	202>263	293>285	285	285
Pass	STIN	Start	158	104>154	154	158
		End	158	154	108>158	158
Grain	FLVA	Start	266	266	266	266
		End	266	271>266	266	266
Exp Gds	STIS	Start	236	236	236	236
		End	236	236	236	237>236
Exp Gds	FLTO	Start	294	294	294	294
		End	294	294	294	294
Ore	STIE	Start	260	260	260	260
		End	256>260	260	260	260
	HUNT	Start	- > 205 > 841 > 256 > -	-	-	205 > 841 > 256
		End	0	-	-	-
Coal	STIW	Start	277	277	277	277
		End	277	277	228>277	277
Exp Gds	STIP	Start	245	245	245	245
		End	245	245	246>245	246>245
Oil	STIV	Start	233	233	233	233
		End	233	232>233	233	233